

# Uddeholm Tyrax<sup>®</sup> ESR

## Welding recommendations

### GENERAL

Uddeholm Tyrax ESR is a premium high hardness and corrosion resistant plastic mould steel. It is designed with very high ductility/toughness and is easy and fast to polish to the highest surface finish levels.

Uddeholm Tyrax ESR is a part of the Uddeholm Stainless Concept.

Good results when welding can be achieved if proper precautions are taken (joint preparation, choice of consumables and welding procedure). If the tool is to be polished, it is necessary to use a filler material that has the same chemical composition as the base material.

### RECOMMENDED FILLER MATERIAL

Welding Method	Gas Tungsten Arc Welding GTAW (TIG)	Gas Metal Arc Welding GMAW (MIG/MAG)	Shielded Metal Arc Welding SMAW (MMA)	Laser	Comments
Filler material	Mirrax TIG Weld Stavax TIG Weld Tyrax TIG Weld	Mirrax MIG Weld Tyrax MIG Weld	Böhler FOX 20 MVW	Tyrax Laser Weld	Tyrax TIG Weld and Tyrax Laser Weld is recommended when the surface are going to be polished or photo-etched
	Type AWS ER 312 AWS ER NiCrMo-3		E 29 9 R		Use soft filler material for buffering layer
Hardness as welded	48 – 58 HRC	48 – 58 HRC	48 – 52 HRC	55 – 58 HRC	

### DIMENSIONS FILLER MATERIAL

Type	TIG		MIG	MMA			Laser
Dia. Ø mm	1.0	1.6	1.2	2.5	3.25	4.0	0.2 – 0.6
Dia. Ø Inch	0.040	1/16	3/64	3/32	1/8	5/32	0.008 – 0.024
Tyrax TIG Weld		X					
Stavax TIG Weld	X	X					
Mirrax TIG Weld	X	X					
Tyrax MIG Weld			X				
Mirrax MIG Weld			X				
Böhler FOX 20 MVW				X	X	X	
Tyrax Laser Weld							X

### PARAMETERS

Condition	Soft Annealed 160 HB	Hardened 45 – 52 HRC	Comment
Preheating Temperature	250°C ± 25°C 480°F ± 50°F	250°C ± 25°C 480°F ± 50°F	The temperature should be kept constant during the welding operation. Start with buffering layers if not all cracks are removed
Interpass temperature	Max 150°C, 270°F above preheating temperature	Max 150°C, 270°F above preheating temperature	The temperature of the tool in the vicinity of the weld. When passed, the tool will have a risk for distortion, soft zones or cracking in and around the weld (the HAZ).
Cooling rate	20 - 40°, 35 - 70°F C/h The first 2 hours then freely in air <70°C, 160°F		
Post treatment	Soft anneal Harden Temper	Temper 25°C, 50°F below previous tempering temperature	Holding time when tempering, 2h. The temperature depends on the last used tempering temperature. When soft annealing and hardening, see heat treatment specification in Uddeholm Tyrax product brochure.*

\* Note. We have seen that in many cases a high temperature tempering, 2h, of ~750°C (1380°F) functions instead of a complete soft annealing when welding in soft annealed material.

## PROCEDURES

- Clean weld area.
- Preheat material to  $250^{\circ}\text{C} \pm 25^{\circ}\text{C}$  /  $480^{\circ}\text{F} \pm 50^{\circ}\text{F}$  and maintain temperature during welding.
- Do not let the temperature in the vicinity of the weld (the HAZ) increase more than  $150^{\circ}\text{C}$  /  $270^{\circ}\text{F}$  above the preheating temperature. There is a risk of lowering (softening) the hardness of the base material or/and cracking in the HAZ. Use temple sticks or other temperature-measuring devices.
- For finishing layers use consumables which give suitable hardness.
- Wait a few minutes between each layer of strings, both for soft and hard filler, in order to let the layer equalize and minimize stresses, if possible use pre-heating furnace. Peen to minimize stresses.
- If possible, change welding direction  $180^{\circ}$  between each layer.
- Cool slowly after welding,  $20 - 40^{\circ}\text{C}/\text{h}$ ,  $35 - 70^{\circ}\text{F}/\text{h}$  for the first two hours and then freely in air  $< 70^{\circ}\text{C}$  /  $160^{\circ}\text{F}$ .
- Temper  $25^{\circ}\text{C}$  /  $50^{\circ}\text{F}$  below previous tempering temperature for two hours.
- Tools welded in the annealed condition must undergo a full soft annealing immediately after welding. Allow tool to cool to room temperature before soft annealing. If a complete soft annealing cannot be done, which we recommend, a high temperature tempering at  $750^{\circ}\text{C}$  /  $1380^{\circ}\text{F}$  could be used. Be aware of that the working properties of the material will be somewhat reduced, if the high temperature tempering is used instead of the soft annealing.

Use these guideline recommendations along with  
“Welding of Uddeholm Tool Steel” for complete instructions.